

From: [Moore, Gary](#)
To: ["Gavlas, Sean"](#)
Subject: FW: F.J. Doyle Salvage Stie
Date: Monday, October 01, 2018 12:52:00 PM

From: Mickunas, Dave
Sent: Monday, October 01, 2018 12:35 PM
To: Powell, Greg <Powell.Greg@epa.gov>
Cc: Moore, Gary <Moore.Gary@epa.gov>; Singhvi, Raj <Singhvi.Raj@epa.gov>; Blaze, Stephen <Blaze.Stephen@epa.gov>
Subject: Re: F.J. Doyle Salvage Stie

To do due diligence, I think that you would want to analyze for dioxin.

Sent from my iPhone

On Oct 1, 2018, at 9:08 AM, Powell, Greg <Powell.Greg@epa.gov> wrote:

If you look for them you will probably find some of the isomers of dioxin. I'll forward to our chemists.

Steve ,Dave and Raj any input?

Greg Powell
USEPA-ERT
Erlanger, KY Office
(859)594-6549 office
(513)607-1572 cell

"Facts do not cease to exist because they are ignored."

From: Moore, Gary
Sent: Monday, October 01, 2018 11:47 AM
To: Powell, Greg <Powell.Greg@epa.gov>
Subject: F.J. Doyle Salvage Stie

Greg:

Can you get this to the right person if not you?

We are going to be demolishing a building at a former PCB dismantling facility. They did do cutting and grinding on the transformers. It is a metal building with wood structures.

We are going to do the following: Asbestos Inspection – Required for Reno/Demo
We are planning on doing PCB wipe samples to include analysis for Aroclor 1268

(Galbestos?)

We are going to sample for lead paint

Question: Is there a need to include Dioxins/Furans for the wipe samples?

Thanks

Gary W. Moore (6SF-ER)
Federal On-Scene Coordinator
U.S EPA Region 6
1445 Ross Ave, Suite 1200
Dallas, TX 75202-2733
Cell: 214.789.1627
moore.gary@epa.gov